

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CR473
NW
1/2-1
0.738 mi.
3899 ft.

ON PUBLIC STREET
2740 CROPSY AVE
BROOKLYN, NY
Site 1 of 3 in cluster CR

NY Spills S118461838
N/A

Relative:
Higher

Actual:
5 ft.

SPILLS:

Name: ON PUBLIC STREET
Address: 2740 CROPSY AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1510805 / 2016-02-12
Facility ID: 1510805
Facility Type: ER
DER Facility ID: 476775
Site ID: 522504
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2016-02-08
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 2016-02-08
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2016-02-08
Spill Record Last Update: 2016-02-12
Spiller Name: MICHAEL SAVINO
Spiller Company: JOHN DITORO
Spiller Address: 2740 CROPSY AVE
Spiller Company: 999
Contact Name: MICHAEL SAVINO
DEC Memo: "2/8/16-Zhune spoke to Michael Savino from Statewide Oil 646-996-0108. Michael said Equipment failure on the truck caused the spill while making a delivery. Approximately 30 gallons of oil #4 spilled onto the middle of the street. No soil, no sewer impacted. Statewide is cleaning the spill. 2/12/15-Zhune spoke to Michael Savino to confirm the spill is clean. Michael said the spill had been cleaned. Michael emailed pictures of the site after the clean up. Spill Closed."
Remarks: "in the process of cleaning up the spill"

All Materials:

Site ID: 522504
Operable Unit ID: 1271520
Operable Unit: 01
Material ID: 2275762
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: G
Recovered: Not reported
Oxygenate: Not reported